


Freeze Check Thermolabels



The Freeze Check ThermoLabel is used to indicate an out of range temperature excursion below 32°F (0°C). When the temperature drops below the threshold, the indicator changes irreversibly from clear to white and the green check mark is no longer visible.

- Indicates temperature abuse for products that are sensitive to lower limit temperature excursions.
- Adhesive labels can be applied to a product, package, carton or master pack.
- Tamperproof method for verifying when freeze damage has occurred during shipping, storage, or handling.

| | |
|----------------------|---|
| Response Temperature | 0°C /32°F |
| Temperature Accuracy | +0°F/-2.7°F (+0°C/-1.5°C) |
| Size | 1.125" x 2.375" |
| Characteristics | Irreversible color change from clear to white and the green check mark is no longer visible |
| Storage | Room temperature or below |
| Shelf Life | 2 years, stored in a cool, dry place |

09/15/09 Rev. 2.2